R. 60.00 Lakhs

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

Date : 17/08/202

No. 817

1. Customer's Name and Address With Telephone No. : AEE. BBMP Byatarayanapura, Su
2. Well Location : Prashanthi Nagara 3rd C
3. Total Well Depth / Drilled in Ft. : (375 MM) 1230 feet
4. Casing Erected in Ft. : (56 MM). 183 feet
5. Water Struck at the Depth of : (360 MM) 1180 feet.
6. Total Yield (Measuring method "V" North 2 inch. / inches on " V" North)
7. Formation of Soil / Well Water Condition : Boulders / Silt / Loose Soil / Clear clean.
8. At the Depth of : (362 MM) 1187 feet
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

Assistant Executive Engineer
Byatarayanapura Sub Division
Bangalore-560024

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Manager / Proprietor

Party's Signature

Scanned with CamScanner

VINAYAKA ENTERPRISES

BOREWELL COMPLETION REPORT

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. 818

Date : 20/08/2021

1. Customer's Name and Address With Telephone No. : AEE BBMP Byatarayanapura Sub Division
2. Well Location : Javeri nagara 4th Cross
3. Total Well Depth / Drilled in Ft. : (365 mm) 1197 feet.
4. Casing Erected in Ft. : (62 mm) 203 feet.
5. Water Struck at the Depth of : (360 mm) 1180 feet.
6. Total Yield (Measuring method "V" North 2 inch / inches on " V" North)
7. Formation of Soil / Well Water Condition : Boulders / Silt / Loose Soil / Clear : Clear.
8. At the Depth of : (361 mm) 1184 feet.
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

Assistant Executive Engineer
Byatarayanapura Sub Division
Bangalore-560024

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Manager / ~~Proprietor~~

Party's Signature

Scanned with CamScanner

VINAYAKA ENTERPRISES

BOREWELL COMPLETION REPORT

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. 819

Date : 19/08/2021

1. Customer's Name and Address : AEE BBMP
   With Telephone No. Byatarayanapura Sub Divisio
2. Well Location : Ashwathnagara Mamatha Scann Road.
3. Total Well Depth / Drilled in Ft. : (360 MW) 1180 feet
4. Casing Erected in Ft. : (58 MW) 190 feet
5. Water Struck at the Depth of : Failure.
6. Total Yield (Measuring method "V" North — / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear —
8. At the Depth of : —
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump —

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Assistant Executive Engineer
Byatarayanapura Sub Division
B.B.M.P. Bangalore-560024

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / ~~Proprietor~~

Scanned with CamScanner